



LEAD FREE MATERIAL SAFETY DATA SHEET

I. MATERIAL IDENTIFICATION

COMPANY: TORREY S. CRANE CO PO BOX 374 492 SUMMER ST PLANTSVILLE, CT. 06479	EMERGENCY PHONE: CALL: CHEMTREC 1 800-424-9300	INGREDIENTS: SEE LABEL ON CONTAINER OR SPOOL
TRADE NAME: LEAD FREE SOLDER TB1	CHEMICAL NAME: TIN/COPPER/SILVER/	FORM OF PRODUCTS: BARS, SOLID WIRE, RIBBON

II. CHEMICAL COMPOSITION

TB1 SOLDER CONTAINS THE FOLLOWING INGREDIENTS:				
ELEMENT	CAS NUMBER	RANGE-%	OSHA PERMISSIBLE EXPOSURE LIMIT - 8 HOUR TWA	ACGIH THRESHOLD LIMIT VALUE - 8 HOUR TWA
Copper	7440.50-8	0 - 5	0.1 mg/m3 Fume	0.2 mg/m3 Fume
Silver	7440-22-4	0 - 5	0.01 mg/m3	0.01 mg/m3
Tin	7440-31-5	0 - 100	2 mg/m3	2 mg/m3

III. PHYSICAL DATA

Physical State: (normal Conditions) SOLID		Appearance and Odor: METALLIC GRAY - ODORLESS	
LIQUIDUS- 527°F SOLIDUS-428°F	Boiling Point: N.A.	Vapor Pressure: N.A.	Density: 0.2656 lb. per cu inch

IV: FIRE AND REACTIVITY DATA

Flash Point: N.A.	Flammable Limits: N.A.	Reactivity: TB1 is a stable non-hazardous solid at room temperature
----------------------	---------------------------	--

CAUTION: NEVER USE WATER AS AN EXTINGUISHING MEDIA IN AREAS NEAR MOLTEN METAL
--

V. HEALTH HAZARD DATA

overheating of alloy can produce metal fumes and oxides. Machining operations such as grinding, sawing, buffing can generate airborne particulate in work area. The exposure levels indicated in section II are relevant to these and other operations. Following are symptoms of overexposure to the various ingredients:

Copper	Exposure to fume may cause dryness of throat, fatigue, head and body ache, chill and fever.
Silver	Argyria a blue-gray discoloration of the skin, mucous membranes, and eyes may result from inhalation of silver
Tin	Dust of tin oxide may cause pneumoconiosis.

FIRST AID: Burns from molten metal should be treated as you would a burn from hot grease, cool exposed area with water and seek medical attention. Overheating of metal may generate fumes and/or particulate. If overexposure is suspected employee should be removed from area and a physician consulted. Ingestion of appreciable quantities of alloy is unlikely to occur.

VI. SPILL PROCEDURES

No special precautions are required for spills of bulk material. Scrap alloy can be reclaimed for reuse. Follow Federal, State and local regulations for disposal.

VII. SPECIAL PROTECTION INFORMATION

Where dust or fume levels are in excess of levels in Section II NIOSH approved respiratory protection should be used. Heat resistant gloves should be worn when working with molten alloy. Eye protection should be worn during soldering operation.

VIII. SPECIAL PRECAUTIONS

Practice good personal hygiene. Wash hands thoroughly before eating, smoking or applying cosmetics.

Adequate ventilation should be used when material is in molten or dusty state.

SARA TITLE III SECTION 313 SUPPLIER NOTIFICATION

Solder alloys contain chemicals subject to the reporting requirements of Section 313 of Title III of the Superfund Amendments and Reauthorization Act of 1985 and 40 CFR Part 372.

DATE ISSUED:01/08/14

PREPARED BY: DAVID E. BAKER, PRESIDENT

The information in this MSDS was obtained from sources which we believe are reliable. However, the information is provided without any representation or warranty, express or implied regarding the accuracy or correctness. The conditions or methods of handling, storage, use and disposal of the product are beyond our control and may be beyond our knowledge. For this and other reasons, we do not assume responsibility and expressly disclaim liability for loss, damage or expense arising out of or in any way connected with the handling, storage, use or disposal of the product.